

**Inspection Photos**  
**Location Name: Caster 8-59-19 PAD**  
**Location ID: 452871**



**Photo 1 – Tank Battery**



**Photo 2 – Separators**

Inspection Photos  
Location Name: Caster 8-59-19 PAD  
Location ID: 452871



Photo 3 – Tank Battery Sign




Photo 2 – Stained Soil at 24-6 Wellhead

Inspection Photos  
Location Name: Caster 8-59-19 PAD  
Location ID: 452871



Photo 5 – Stained Soil at 24-16 Wellhead

Photo 6 – Stained Soil at 24-16 Wellhead

**Inspection Photos**  
**Location Name: Caster 8-59-19 PAD**  
**Location ID: 452871**



**Photo 7 – Compressor Day Tank – Netting is in disrepair**



**Photo 8 – Stained Soil at Compressor Day Tank**

**Inspection Photos**  
**Location Name: Caster 8-59-19 PAD**  
**Location ID: 452871**



**Photo 9 – Compressor Drain Pit – Missing Signage and Stained Soil**



**Photo 10 – Oily Waste at Re-Cycle Pump**

**Inspection Photos**  
**Location Name: Caster 8-59-19 PAD**  
**Location ID: 452871**



**Photo 11 – Oily Waste at Produced Water Tanks**

**Photo 12 – Oily Waste at Produced Water Tanks**