

**Inspection Photos**  
**Location Name: Timbro 9-59 #8B PAD**  
**Location ID: 456879**



Colorado Oil and Gas Conservation Commission  
40.76203, -104.00927, 4980.3ft, 297°  
11/10/2020 12:26:59

**Photo 1 – Tank Battery**



Colorado Oil and Gas Conservation Commission  
40.7622, -104.00927, 4822.7ft, 198°  
11/10/2020 12:17:38

**Photo 2 – Separators**

**Inspection Photos**  
**Location Name: Timbro 9-59 #8B PAD**  
**Location ID: 456879**



**Photo 3 – Tank Battery Sign**



**Photo 4 – Wellheads, Unused Downhole Tools and Tubing**





Inspection Photos  
Location Name: Timbro 9-59 #8B PAD  
Location ID: 456879



Photo 5 – VRUs



Photo 6 – Gas Meter Calibration Card



**Inspection Photos**  
**Location Name: Timbro 9-59 #8B PAD**  
**Location ID: 456879**



**Photo 7 – Stained Soil at Compressor**




**Photo 6 – Stained Soil at Compressor**



**Inspection Photos**  
**Location Name: Timbro 9-59 #8B PAD**  
**Location ID: 456879**



**Photo 9 – Stained Soil at Compressor**



**Photo 10 – Unused Workover Rig Equipment in SE corner of Location**