

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/05/2020

Submitted Date:

11/12/2020

Document Number:

699601992

FIELD INSPECTION FORM

Loc ID 304044 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10699
Name of Operator: OWN RESOURCES OPERATING LLC
Address: 38 PALMER CREST CT
City: SPRING State: TX Zip: 77381

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Dolezal, Pat		pat.dolezal@ownresources.com	Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
253986	WELL	PR	11/20/1996	GW	125-07864	KLINZMAN 9-11	PR

General Comment:

[Routine FIR](#)

Location

Lease Road:			
Type	Access		
comment:	Two track grassland		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	MR		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Satisfactory		
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No	
Comment:	NA
<input type="checkbox"/> Multiple Spills and Releases?	

Fencing/:			
Type	WELLHEAD		
Comment:	Steel pipe		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 0		
Comment:	No change in equipment inventoried		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Calibration cert in place		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:	NA		
Corrective Action:		Date:	

Flaring:			
Type			

Comment:	NA	
Corrective Action:		Date:

Inspected Facilities

Facility ID: 253986 Type: WELL API Number: 125-07864 Status: PR Insp. Status: PR

Producing Well

Comment: [FGW](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Use BMP's](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT