

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/12/2020

Submitted Date:

11/12/2020

Document Number:

698702159

**FIELD INSPECTION FORM**

Loc ID 437468 Inspector Name: Serna, Abe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
437470	WELL	PR	08/01/2020	OW	123-39549	Heartland State G36-75-1HN	PR
437471	WELL	PR	08/01/2020	OW	123-39550	Heartland State H01-74-1HNX	PR
437472	WELL	PR	08/01/2020	OW	123-39551	Heartland G25-73-1HN	PR
437473	WELL	PR	08/01/2020	OW	123-39552	Heartland State H01-73-1HN	PR
437474	WELL	PR	08/01/2020	OW	123-39553	Heartland State C31-79-1HN	PR
437475	WELL	PR	08/01/2020	OW	123-39554	Heartland C31-78-1HN	PR
437476	WELL	PR	08/01/2020	OW	123-39555	Heartland C30-79-1HN	PR
437477	WELL	PR	08/01/2020	OW	123-39556	Heartland C30-79HN	PR
437478	WELL	PR	08/01/2020	OW	123-39557	Heartland G25-72-1HN	PR

**General Comment:**

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

**Equipment:**

			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	437470	Type:	WELL	API Number:	123-39549	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	437471	Type:	WELL	API Number:	123-39550	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	437472	Type:	WELL	API Number:	123-39551	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	437473	Type:	WELL	API Number:	123-39552	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	437474	Type:	WELL	API Number:	123-39553	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	437475	Type:	WELL	API Number:	123-39554	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	437476	Type:	WELL	API Number:	123-39555	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				
Facility ID:	437477	Type:	WELL	API Number:	123-39556	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	PR								
Corrective Action:					Date:				

Facility ID:	<u>437478</u>	Type:	<u>WELL</u>	API Number:	<u>123-39557</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
--------------	---------------	-------	-------------	-------------	------------------	---------	-----------	---------------	-----------

**Producing Well**

Comment:	<u>PR</u>	
Corrective Action:		Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On (11/12/2020) at approximately (10:20 HRS), I, Inspector (Abe Serna),                      Conducted an on-site inspection at (Heartland G25-72-1HN) (Noble Energy), at                      (Location #437468) in (Weld County) Colorado.                      While there, I observed a (PR Well)                      During this inspection compliance issues were observed.                      No follow up on this site inspection needs to be conducted.                      This is a summary of inspection report.</p>	sernaa	11/12/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698702160	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5290522">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5290522</a>