

Inspection Photos  
Operator: BP America  
API: 067-06686 Date:  
11/10/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward,



Photo 3. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with grasses such as crested wheatgrass, smooth brome, and sand dropseed.



Photo 4. View of reference area, grass field, largely snow covered at this time.



Photo 5. View of closed gate after leaving location.