

**Inspection Photos**  
**Operator: BP America**  
**API: 067-06140**  
**Date: 11/10/2020**



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with grasses such as smooth brome and sand dropseed.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of reference area, comprised of a cultivated field that is fallow at this time.