Pit Status Evaluation Form

Pit Overview:

Pit Name: Gary Gebauer 2 **Facility ID:** 117719

Current Status: Unknown **Status Date:** 9/23/1999

Current Operator: PADCO LLC 24500

Updated Operator:

Form 15 Pit Permit Doc #: 691626 **Permit Date:** 10/03/1988

Related Facilities:

County:

Township: 1N **Range:** 53W **Section:** 14 **QQ:**

Original Latitude/ Longitude: 40.032426 / -103.266751

Updated Latitude/ Longitude: 40.045339 / -103.265059

Basis for Location Change:

Pit symbol originally co-located with 121-08278, Pit Permit indicates Section 14.

Pit Inspection/Information Request:

Field Inspection Date: **Document #:**

Pit Still Present in Field: No

Visible Surface Impacts: ☐ Stressed Vegetation ☐ Surface Depression ☐ Stained Soil ☐ Other (see below)

Inspection Notes:

Operator Required to Submit Form: NA **Due Date:**

Form Request Sent To: **Sent Date:**

Pit Status Evaluation:

Pit Status Review Documents:

- [ ] **Form 15 Pit Permit – Doc #:** 691626 **Date:** 10/03/1988
- [ ] **Field Inspection(s) – Doc #:** **Date:**
  - **Doc #:** **Date:**
  - **Doc #:** **Date:**
- [ ] **Form 27 Remediation Workplan – Project #:** **Date:**
- [ ] **Form 4 Sundry Notice – Doc #:** **Date:**
- [ ] **COGIS Document – Doc #:** **Date:**
- [ ] **Pit Inventory – Doc #:** **Date:**
- [ ] **Duplicate Record – Duplicate Pit(s) #:**
- [ ] **Aerial Photo Verification (photos attached)**
- [ ] **Other:**

Pit Status Determination

Updated Pit Status: Active **Pit Status Date: 11/13/2020**

Timing of Pit Closure:

Pit Status Review Summary:

Pit symbol originally co-located with 121-08278, 11/16/1998 letter includes a facility layout diagram that shows the pit in Section 14. Rem #7798 documents the closure of the former oil skim pit.