

**Inspection Photos**  
**Operator: BP America**  
**API:067-08945**  
**Date: 11/10/2020**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern entrance facing northward. Revegetation is progressing with western wheatgrass, intermediate wheatgrass, and crested wheatgrass. Equipment in photo is not stored within the project area.



Photo 3. View of area in the southern project area where berm and silt trap installed.