

# Inspection Photos

Operator: BP America  
API: 067-07694  
Date: 11/10/2020



Photo 1. View of the project area from the well pad entrance facing center.





Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass, intermediate wheatgrass, smooth brome, and crested wheatgrass.





Photo 3. View of reference area (in background) comprised of pinyon/juniper woodland with understory of sagebrush, mountain mahogany, western wheatgrass, James galleta.