

Inspection Photos

API#045-07349

Operator: Caerus

Inspection #: 692402523

Inspection Date: 9/18/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to East.

September 18, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Mamm Creek API#045-07349



Photo#2:
Overview of Location to North.

September 18, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Mamm Creek API#045-07349



Photo#3:
View od North end of Location; area bare of vegetation

September 18, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Mamm Creek API#045-07349



Photo#4:

Area of Location with some establishment of perennial species though weeds growth is interspersed.

September 18, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Caerus PA Mamm Creek API#045-07349



Photo#5:
Weedy areas of site.



Photo#6:
Weedy areas of site.

September 18, 2020



Photo#7:
Area bare of vegetation at Pad perimeter.

September 18, 2020



Photo#8:
Slope vegetation sparse.



Photo#9:
Road is stable.

September 18, 2020



Photo#10:
Road is stable