

MARALEX RESOURCES, INC.– 53255
API# 05-077-08557 CAMP GULCH UNIT-FEDERAL #1-24-8-103
Inspection Date : 11/13/2020



Wellhead during MIT operations



Separator , meter housing , tank and blowdown pit.

MARALEX RESOURCES, INC.– 53255
API# 05-077-08557 CAMP GULCH UNIT-FEDERAL #1-24-8-103
Inspection Date : 11/13/2020



Gauge at start of test



Gauge at 5 mins

MARALEX RESOURCES, INC.– 53255
API# 05-077-08557 CAMP GULCH UNIT-FEDERAL #1-24-8-103
Inspection Date : 11/13/2020



Gauge at 10 mins



Gauge at 15 mins

MARALEX RESOURCES, INC.– 53255
API# 05-077-08557 CAMP GULCH UNIT-FEDERAL #1-24-8-103
Inspection Date : 11/13/2020



Form 21 field copy