

Inspection Photos

API: 071-08233

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/13/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08233 | Date: 11/13/2020

Inspection Photos



Photo 1. Facing toward the well which is inside the shed. There is water leaking from the well and flowing down the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08233 | Date: 11/13/2020

Inspection Photos



Photo 2. Facing inside well shed. There is a dripping water leak from the well head.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08233 | Date: 11/13/2020