

Inspection Photos

API: 071-09246

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/13/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09246 | Date: 11/13/2020

Inspection Photos



Photo 1. Facing southwest the beginning of the access road. The access road has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 11/13/2020

Inspection Photos



Photo 2. Facing southwest along the access road. The electric utility remains along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 11/13/2020

Inspection Photos



Photo 3. Facing south along the access road. The electric utility remains along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 11/13/2020

Inspection Photos



Photo 4. Facing southeast. The access road split to the location in the left side of photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 11/13/2020

Inspection Photos



Photo 5. Facing southeast along the access road toward the location. The electric utility remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 11/13/2020

Inspection Photos



Photo 6. The electric utility has not been removed. There was a buzzing noise heard from the utility which indicates it active.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 11/13/2020

Inspection Photos



Photo 7. Facing east at the location. There is gravel that remains at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 11/13/2020

Inspection Photos



Photo 8. Facing southwest at the location. The vegetation has not adequately established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 11/13/2020

Inspection Photos



Photo 9. Facing west at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09246 | Date: 11/13/2020