

# Inspection Photos

API: 071-08290

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/13/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08290 | Date: 11/13/2020

## Inspection Photos



**Photo 1.** Facing northwest the beginning of the access road. The road appears to be pre-existing however, there are signs of stormwater erosion down the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08290 | Date: 11/13/2020

## Inspection Photos



**Photo 2.** There is erosion rilling down the road that will need to be repaired.



## Inspection Photos



**Photo 3.** Facing southwest along the access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08290 | Date: 11/13/2020

## Inspection Photos



**Photo 4.** Facing southwest toward the location. The location has not been recontoured.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08290 | Date: 11/13/2020

## Inspection Photos



**Photo 5.** Facing south toward the location.



## Inspection Photos



**Photo 6.** Facing northeast toward the location.



## Inspection Photos



**Photo 7.** Facing southwest at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08290 | Date: 11/13/2020