

Inspection Photos
Operator: BP America
API: 067-08806
Date: 11/13/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with western wheatgrass, smooth brome, James galleta, and sand dropseed.



Photo 3. View of reference area comprised of open pinyon and juniper woodland with understory of sagebrush and grasses/forbs such as James galleta, purple threeawn, thickspike wheatgrass, and snakeweed.