

Inspection Photos

Operator: BP America
API: 067-06344
Date: 11/13/2020



Photo 1. View of the project area from the southwestern corner facing eastward. Revegetation is progressing with grasses and shrubs such as thickspike wheatgrass, rubber rabbitbrush, and purple threeawn.



Photo 2. View of the eastern project area from the southeastern corner facing northward.



Photo 3. View of reference area comprised of sagebrush shrubland with purple threeawn, James galleta, thickspike wheatgrass, and prickly pear.