

Inspection Photos
Operator: BP America
API: 067-06244
Date: 11/13/2020



Photo 1. View of the project area from the northeastern corner facing center. Revegetation is progressing with grasses and shrubs such as thickspike wheatgrass, rubber rabbitbrush, and purple threeawn.



Photo 2. View of the northern project area from the northeastern corner facing westward.



Photo 3. View of musk thistles within the northern project area. Approximately 150 individuals observed.



Photo 4. View of reference area comprised of pinyon and juniper woodland with sagebrush understory, crested wheatgrass, purple threeawn, and blue grama.



Photos 5/6. View of closed gates after entering (left) and leaving (right) location.