

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402534529

Date Received:

11/17/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

.Grizzly

aaxelson@grizzlyenergyllc.com

.Grizzly

sghan@grizzlyenergyllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700701757

Inspection Date: 10/23/2020

FIR Submit Date: 10/24/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC

Company Number: 10531

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 413567

Location Name: THARP Number: 41D-23-692 County: \_\_\_\_\_

Qtrqtr: NENE Sec: 23 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.519033 Longitude: -107.625743

FACILITY - API Number: 05-045-00 Facility ID: 413567

Facility Name: THARP Number: 41D-23-692

Qtrqtr: NENE Sec: 23 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.519033 Longitude: -107.625743

CORRECTIVE ACTIONS:

1 CA# 143933

Corrective Action: remove staining and maintain equipment

Date: 11/13/2020

Response: CA COMPLETED

Date of Completion: 10/30/2020

Operator Comment: CA completed

COGCC Decision: \_\_\_\_\_

Operator	chemical tanks removed
Comment:	

COGCC Representative:

Operator Comment:	Removed wattles, cleaned and replaced check dams, and installed additional gravel to stabilize combustor area.
-------------------	--

COGCC  
Representative:

Comment:

Title: Senior EHS Specialist Date: 11/17/2020 1:40:58 PM

Page 2 of 2