FORM 5A Rev 06/12	State of Colo Oil and Gas Conservatio 1120 Lincoln Street, Suite 801, Denver, Colorado 80203 2109 COMPLETED INTERV	Commi Phone: (303) 894	-2100 Fax: (303) 89		ET OE ES pocument Number: 401749753		
The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to 05/29/2020 05/29/2020							
1. OGCC Operator Number: 10177 4. Contact Name: Carolyn Nunez 2. Name of Operator: ENERPLUS RESOURCES (USA) CORPORATION Phone: (720) 279-5583 3. Address: 950 17TH STREET #2200 Fax: Email: cnunez@enerplus.com							
5. API Number 05-123-44595-00 6. County: WELD 7. Well Name: CHERRY CREEK Well Number: 8-67-28-27N 8. Location: QtrQtr: SWSW Section: 28 9. Field Name: DJ HORIZONTAL NIOBRARA Field Code: 16950							
Completed Interval FORMATION: NIOBRARA Status: PRODUCING Treatment Type; FRACTURE STIMULATION Treatment Date: 06/05/2018 End Date: 06/27/2018 Date of First Production this formation: 07/29/2018 Perforations Top: 8192 Bottom: 17141 No. Holes: 1560 Hole size: 0.42 Provide a brief summary of the formation treatment: Open Hole:							
Date: _ Calculat Test Me Gas Dis Tubing S Reason	ted 24 hour rate: Bbl oil: 256 Mc thod: Flowback Casing position: FLARED Gas Size: 2 + 3/8 Tubing Setting Depth: 76 for Non-Production:	Type: DRY 613 Tbg	Bbl H2O: Tubing PSI: Btu Gas: _1 setting date:07/23/2	936 0 515 Choke 468 API Gravit 2018 Packer D	y Oil: 38		
Date formation Abandoned: Squeeze: Yes No If yes, number of sacks cmt ** Bridge Plug Depth: ** Sacks cement on top: ** Wireline and Cement Job Summary must be attached.							

Comment:							
I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.							
Signed:	Signed: Print Name: Carolyn Nunez						
Title: Drillin	g Eng Tech Date: 5/29/2020 Email cnunez@enerplus.com						
Attachment List							
Att Doc Num	Name						
401749753	FORM 5A SUBMITTED						
401749852	WELLBORE DIAGRAM						
Total Attach: 2	Files						
General Comments							
<u>User Group</u>	Comment	Comment Date					
Permit	Pass.	11/18/2020					
Permit	Corrected choke size per operator.	10/29/2020					
Permit	Frac Focus dates corrected. Corrected GOR. Choke size incorrect. Form 7 reporting is delinquent/incorrect. Missing 4/2018, 5/2018, 8/1/2019, 6/1/2020- needs to go back to spud date. 30 days of production in July suspect.	10/13/2020					
Engineer	F42 start date 6/3; FF dates still don't align with this Form 5A - provide an explanation of dates for treatment and provide a contractor's job summary for the dates indicated (attachment) - Form 7 still not corrected back to April 2018 - July 2018 says 30 days production - is that correct, IP given as 7/13?04/1						
Engineer	FF dates don't agree with these 5A dates (or Form 42, though closer) - Form 7 reporting not corrected after being cited as needing to be back to spud 4/24/2018						
Engineer	ineer operator requested return to DRAFT for corrections						
Total: 6 comm	ient(s)						