

Inspection Photos

API: 043-06222

Operator: INCREMENTAL OIL & GAS
(FLORENCE) LLC

Inspection Date: 11/17/2020



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06222 | Date: 11/17/2020

Inspection Photos



Photo 1. Facing northwest toward the former access road. There was minimal vegetation beginning to establish along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06222 | Date: 11/17/2020

Inspection Photos



Photo 2. Facing northwest toward the location. Most of the vegetation observed was Russian thistle (undesirable weeds). There was some desirable vegetation observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06222 | Date: 11/17/2020

Inspection Photos



Photo 3. The wattles around the perimeter of the location are displaced and not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06222 | Date: 11/17/2020

Inspection Photos



Photo 4. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06222 | Date: 11/17/2020

Inspection Photos



Photo 5. View of ground cover. Arrow points to desirable species beginning to establish.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06222 | Date: 11/17/2020

Inspection Photos



Photo 6. The wattles around the perimeter of the location are displaced and not maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06222 | Date: 11/17/2020