

Inspection Photos
Location Name: Carl A miler B #10
Location ID: 318378



Photo 1 WH Debris: dead weeds around well site



Photo 2 Sign is not posted properly and contact number has peeled off. Unused equipment Cement base is not being used.

Inspection Photos
Location Name: Carl A miler B #10
Location ID: 318378



Photo 3 all flow line valves off well head are closed.