

**Inspection Photos**  
**Operator: BP America**  
**API: 067-09442**  
**Date: 11/17/2020**



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing within the project area with western wheatgrass, crested wheatgrass, rubber rabbitbrush, and sand dropseed.



Photo 3. View of reference area comprised of sagebrush and antelope bitterbrush shrubland with scattered pinyon and juniper trees and understory of thickspike wheatgrass, yucca, prickly pear, and narrowleaf penstemon.



Photos 4/5. View of closed gates (2) after leaving location.