

BP L48 San Juan



V2 Compliance Follow Up Form

18162103770

Reference Number:

Form Name:

Submitter Name:

Submission Date:

Location:

20201112-18162103770

V2 Compliance Follow Up Form

Cole Nichols (colen@horizonenvservices.com) |

colen@horizonenvservices.com

Nov 12, 2020 4:19:34 PM MST

91 S Skylane Dr, Durango, CO 81303, USA

Nov 12, 2020 4:19:31 PM MST [[View Map](#)]

INFORMATION

Section 1

Name

colen@horizonenvservices.com

Date

Nov 12, 2020

Well Name

PAYNE, EVELYN GAS UNIT A 2

API Number

50670888000

Select State

Colorado

Work type

COGCC Inspection AR

Action Complete

Seeding

Erosion Repairs

Photo of first corrective action completed



Completed work description Corrective
Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

repaired rills and seeded and blanketed slopes

Photo of third corrective action completed



Completed work description of corrective action 3

seeded and blanketed slopes

Photo of fourth corrective action completed



Completed work description

seeded and blanketed slopes

Completed work description of corrective action 4

repaired rills and seeded and blanketed slopes

Additional photos



Additional photos



Completed work description

seeded and blanketed slopes

Summary of all work completed

seeded and blanketed slopes