

Inspection Photos
Location Name: Linnbur 6-33
Location ID: 320451



Photo #1 Pump Jack.



Photo #2 Stained soil around well head