




40.12833, -108.19977, 6053.0ft, 280°
11/18/2020 01:31:50 PM



Ant Hill Unit Dow 19-24
SENE Sec 19 T-2N, R-96W

40.12867, -108.2003, 6058.5ft, 324°
11/18/2020 01:28:25 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

Ant Hill Unit 19-24

API: 05-103-10219

Inspection: 700404274



40.1283, -108.20015, 6056.3ft, 325°
11/18/2020 01:27:45 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator & meter building.

Ant Hill Unit 19-24

API: 05-103-10219

Inspection: 700404274



40.12849, -108.20006, 6046.1ft, 35°
11/18/2020 01:29:05 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Tanks.

Ant Hill Unit 19-24

API: 05-103-10219

Inspection: 700404274