

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787



Pic 1 No annual bradenhead test on file



Pic 2

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787



Pic 3



Pic 4 stained soil / mechanical issue on oil tank valve

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787



Pic 5 mechanical issue / stained soil on water tank valve



Pic 6 stained soil covered up with dirt in pump house needs removed.

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787

Nov 18, 2020 at 11:54:58 AM
40.077857, -104.889224
387 County Road 19
Fort Lupton CO 80621
United States
COGCC



Pic 7 stained soil covered up with new dirt in pump house needs removed

Nov 18, 2020 at 11:55:18 AM
40.077942, -104.889276
387 County Road 19
Fort Lupton CO 80621
United States
COGCC




Pic 8

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787



Pic 9



Pic 10

Inspection Photos
Location Name: Vera L Mccannon 1
Location ID: 159787

Nov 18, 2020 at 11:58:21 AM
40.077897,-104.889549
387 County Road 19
Fort Lupton CO 80621
United States
COGCC



Pic 11