



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 1. Location.**

**Douglas Creek Unit 48**

**API: 05-103-09314**

**Inspection: 700404290**





39.8183, -108.73983, 6269.6ft, 236°  
11/20/2020 09:38:16 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 2. Well with gas leak.**

**Douglas Creek Unit 48**

**API: 05-103-09314**

**Inspection: 700404290**





39.81832, -108.73985, 6265.1ft, 304°  
11/20/2020 09:38:34 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Gas leak.**

**Douglas Creek Unit 48**

**API: 05-103-09314**

**Inspection: 700404290**