

Inspection Photos
Location Name: Federal-Chamberlin 22-1
Location ID: 312863



Photo 1. Separator too close to tanks.



Photo 2. Overview of location taken facing southeast.

