

Inspection Photos

11/06/2020

Operator: TEP ROCKY MOUNTAIN LLC #
96850

Location ID: 324181
Garfield, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC # 96850
Location ID: 324181



Photo 1: Photo taken from the south end of the Location, facing northwest. Photo shows well site and reclamation area. Unable to find evidence of additional seeding activities and BMPs implemented to stabilize the seeded soils at the well Location and areas of the access road.



Photo 2: Photo taken from the south end of the Location, facing northeast. Photo shows well site and reclamation area. Unable to find evidence of additional seeding activities and BMPs implemented to stabilize the seeded soils at the well Location and areas of the access road.



Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 324181



Photo 3: Photo taken from the Location. Photo shows soil surface at well site and reclamation area. Unable to find evidence of additional seeding activities and BMPs implemented to stabilize the seeded soils at the well Location and areas of the access road.



Photo 4: Photo shows area of the access road, facing north. Unable to find evidence of additional seeding activities and BMPs implemented to stabilize the seeded soils at the well Location and areas of the access road.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC # 96850

Location ID: 324181



Photo 5: Photo taken from the access road. Photo shows soil surface at access road and reclamation area. Unable to find evidence of additional seeding activities and BMPs implemented to stabilize the seeded soils at the well Location and areas of the access road.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources