

Inspection Photos
Location Name: Simms E #1
API: 05-067-07026



Simms E #1 and #3 location photo.



Damp area alongside #3 pump jack, along southern edge of location.

Inspection Photos
Location Name: Simms E #1
API: 05-067-07026



Wet soil behind #3 pump jack.



Damp soil near #3 pump jack from Spill/Release Point ID #478512.

Inspection Photos
Location Name: Simms E #1
API: 05-067-07026



Location appears to have recently been bladed.



Remains of berm reportedly used to prevent spill from leaving location.