

Inspection Photos

11/19/2020

Operator: SG INTERESTS I LTD # 77330

Location ID: 324461

Gunnison, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: SG INTERESTS I LTD # 77330

Location ID: 324461



Photo 1: Photo taken from the access road, facing north. Reclamation in process. Though weeds were not observed in this inspection, due to the onset of winter conditions and plant dormancy it is unclear if sufficient weed management activities have been conducted per the corrective actions. A followup inspection will need to be conducted during the 2021 growing season to determine compliance with Rule 1004.e and corrective actions; Ongoing weed monitoring/management is required until Location passes final reclamation.

Photo 2: Photo taken from the well location, facing east. Reclamation in process. Though weeds were not observed in this inspection, due to the onset of winter conditions and plant dormancy it is unclear if sufficient weed management activities have been conducted per the corrective actions. A followup inspection will need to be conducted during the 2021 growing season to determine compliance with Rule 1004.e and corrective actions; Ongoing weed monitoring/management is required until Location passes final reclamation.