

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /2B Pad

Location ID: 334465



Photo #2286 from entrance to location.



Photo #2287 from entrance to location.

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /2B Pad

Location ID: 334465



Photo #2288 from entrance to location.



Photo #2282 Tracking occurring from location to access road.

Inspection Photos

Location Name: LARAMIE ENERGY LLC NVega /2B Pad

Location ID: 334465



Photo #2283 Sediment is being transported off of location and on to access road.



Photo #2284 access road.