

Inspection Photos
Location Name: Linnbur 6-23
Location ID: 320456




Photo #1 Pump Jack.



Photo #2 stained soil at wellhead.