

Inspection Photos

API: 071-06191

Operator: TIMBER CREEK OPERATING
OGRIS OPERATING LLC

Inspection Date: 11/19/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06191 | Date: 11/19/2020

Inspection Photos



Photo 1. The cattle guard along the main road near the Bingham campground is filled in with sediment. The cattle guard needs to be maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 11/19/2020

Inspection Photos



Photo 2. Stormwater is not properly diverted at the red arrow causing stormwater to pool in the vehicle ruts. This area needs to be repaired. (Lat/Long:37.071679,-104.91145)



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 11/19/2020

Inspection Photos



Photo 3. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 11/19/2020

Inspection Photos



Photo 4. The metal grate at the wellhead is displaced. This area should be maintained and covered to prevent wildlife entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06191 | Date: 11/19/2020