

Inspection Photos

11/19/2020

Operator: GUNNISON ENERGY LLC # 10515

Location ID: 412922

Gunnison, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: GUNNISON ENERGY LLC # 10515

Location ID: 412922



Photo 1: Photo taken from the Location entrance, facing north. Photo shows signage required per Delayed IR Form 4 #401463219 conditions has not been posted, or is not plainly visible.



Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 412922




Photo 2: Photo taken from the west end of the Location, facing north. Photos 2-4 provide an overview of the Location from north, south east to south.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 412922



Photo 3: See comments under photo 2.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC # 10515
Location ID: 412922



Photo 4: See comments under photo 2.