

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/23/2020

Submitted Date:

11/23/2020

Document Number:

693503907**FIELD INSPECTION FORM**

Loc ID 302389 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298430	WELL	TA	05/26/2020	OW	123-29060	Wells Ranch USX AA 13-08	TA

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Good Housekeeping:			
Type	DEBRIS		
Comment:	Dead weeds and tumble weeds inside fenceing remove as soon as possible.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Steel rod.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 298430 Type: WELL API Number: 123-29060 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: Form 4 Doc # 402358867 TA Status on file with the COGCC. Per COGCC Rule 326.b. (1) a successful mechanical integrity test shall be performed on each temporarily abandoned well within thirty (30) days of the date the well becomes incapable of production.

Corrective Action: Date: **BradenHead**Date of Last Brhd Test: Annual Brhd Completed? #ErrorLast Brhd Test Results Initial Surf Csg Pressure: Fluid Type: End Surf Csg Pressure: Comment: Submit reports as per Rule 206.Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<u>Routine inspection</u>	silverr	11/23/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693503908	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5296544