

# *Inspection Photos*


*API#081-07359*

*Operator: Tatonka*


*Insp#: 692402689*

*Insp Date: 11/18/2020*





Photo#1:  
View North over Location.



Photo#2:  
View South over Location.

November 18, 2020



Photo#3:  
View East over Location.



Photo#4:  
View West over Location.

November 18, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Tatonka O&G PA Gerber API#081-07359



Photo#5:  
Overview of Location and close up view of vegetation.

November 18, 2020