

Final Reclamation Inspection

November 12, 2020

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 318311

Inspection Document #: 697502201

Weld County, CO

NESE Section 10 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UPRR 43 PAN AM I #9
Location ID: 318311




Photo 1. Photo taken from the well location, facing North. Photo illustrates the Operator has failed to remove all equipment and perform final reclamation activities.

Inspection Photos
Location Name: UPRR 43 PAN AM I #9
Location ID: 318311



Photo 2. Photo taken from the well location, facing South. Photo illustrates the Operator has failed to perform final reclamation activities for the access road.

Inspection Photos

Location Name: UPRR 43 PAN AM I #9

Location ID: 318311



Photo 3. 2019 aerial imagery using COGCC GISOnline. Imagery illustrates what portions of the access have not been reclaimed.

Note: the access road heading west has not been reclaimed but will be addressed in a separate inspection.