

Final Reclamation Inspection

November 12, 2020

Operator: K P KAUFFMAN COMPANY INC- #46290

Location ID: 318412

Inspection Document #: 697502203

Weld County, CO

NWSE Section 10 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UPRR 43 PAN AM I #20
Location ID: 318412



Photo 1. Photo taken from the well location, facing East. Photo illustrates the Operator has failed to remove all equipment and perform final reclamation activities.

Inspection Photos
Location Name: UPRR 43 PAN AM I #20
Location ID: 318412



Photo 2. Photo taken from the eastern access road, facing West. Photo illustrates the Operator has failed to perform final reclamation activities for the access road.

Inspection Photos
Location Name: UPRR 43 PAN AM I #20
Location ID: 318412



Photo 3. Photo taken from the central access road, facing West. See comments under Photo 2.

Inspection Photos

Location Name: UPRR 43 PAN AM I #20

Location ID: 318412



Photo 4. 2019 aerial imagery using COGCC GISOnline. Imagery illustrates what portions of the access have not been reclaimed.