

Final Reclamation Inspection

November 12, 2020

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 323207

Inspection Document #: 697502205

Weld County, CO

NESE Section 9 T1N R68W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: CHAMPLIN 86 AMOCO I #1
Location ID: 323207



Photo 1. Photo taken from the well location/associated tank battery location, facing West. Photo illustrates the Operator has removed all equipment from the location. Unable to find evidence of oil and gas activities and/or disturbances. Well location/associated tank battery location appear reflective of reference crop areas.



Inspection Photos

Location Name: CHAMPLIN 86 AMOCO I #1

Location ID: 323207



Photo 2. Photo taken from the well location/associated tank battery location, facing North. See comments under Photo 1.



Inspection Photos
Location Name: CHAMPLIN 86 AMOCO I #1
Location ID: 323207



Photo 3. Photo taken from the well location/associated tank battery location, facing South. See comments under Photo 1.



Inspection Photos
Location Name: CHAMPLIN 86 AMOCO I #1
Location ID: 323207



Photo 4. Reference photo taken north of the well location/associated tank battery location, facing North. See comments under Photo 1.

