

Inspection Photos
Location Name: Lundvall #1, J 18-12, 18-6
Location ID: 332893




Photo 1: Tank Battery Sign



Photo 2: Tank Battery



Inspection Photos
Location Name: Lundvall #1, J 18-12, 18-6
Location ID: 332893



Photo 3: Riser removed