

## Pit Status Evaluation Form

### Pit Overview:

<b>Pit Name:</b> E. MAX SERAFINI	<b>Facility ID:</b> 118632
<b>Current Status:</b> Unknown	<b>Status Date:</b> 9/23/1999
<b>Current Operator:</b> AMOCO PRODUCTION COMPANY / 2500	
<b>Updated Operator:</b>	
<b>Form 15 Pit Permit Doc #:</b> 712341	<b>Permit Date:</b> 6/14/1974
<b>Related Facilities:</b> SERAFINI, E. MAX GAS UNIT #1 (API 123-07970; Facility ID 240182; Loc ID 317920)	

<b>County:</b> WELD			
<b>Township:</b> 2N	<b>Range:</b> 68W	<b>Section:</b> 16	<b>QQ:</b> SWSW
<b>Original Latitude/ Longitude:</b> 40.133276 / -105.015317			
<b>Updated Latitude/ Longitude:</b> /			
<b>Basis for Location Change:</b>			

### Pit Inspection/Information Request:

<b>Field Inspection Date:</b>	<b>Document #:</b>
<b>Pit Still Present in Field:</b> No	
<b>Visible Surface Impacts:</b> <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
<b>Inspection Notes:</b>	
<b>Operator Required to Submit Form:</b> NA	<b>Due Date:</b>
<b>Form Request Sent To:</b>	<b>Sent Date:</b>

## Pit Status Evaluation:

### Pit Status Review Documents:

- |                                     |   |                  |
|-------------------------------------|---|------------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 712341          | Date: 6/14/1974  |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 214153         | Date: 6/13/1996  |
|                                     | Doc #: 200104981                            | Date: 1/29/2007  |
|                                     | Doc #:                                      | Date:            |
| <input type="checkbox"/>            | Form 27 Remediation Workplan – Project #:   | Date:            |
| <input type="checkbox"/>            | Form 4 Sundry Notice – Doc #:               | Date:            |
| <input type="checkbox"/>            | COGIS Document – Doc #:                     | Date:            |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2314561              | Date: 12/21/1995 |
| <input type="checkbox"/>            | Duplicate Record – Duplicate Pit(s) #:      |                  |
| <input type="checkbox"/>            | Aerial Photo Verification (photos attached) |                  |
| <input type="checkbox"/>            | Other:                                      |                  |

### Pit Status Determination

**Updated Pit Status: Closed**

**Pit Status Date: 9/23/1999**

#### Timing of Pit Closure:

Pit closed prior to 1995 pit inventory report.

#### Pit Status Review Summary:

Based on records review and aerial imagery, any pits on location were replaced by a steel produced water tank prior to 1995 pit inventory report. Associated well PA 10/1/2014. Pit status has been changed to closed.

