

Pit Status Evaluation Form

Pit Overview:

Pit Name: E. SCHNEIDER "B" 2	Facility ID: 118539
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: AMOCO PRODUCTION COMPANY / 2500	
Updated Operator:	
Form 15 Pit Permit Doc #: 383024	Permit Date: 5/31/1973
Related Facilities: AMOCO-CHARTER-SCHNEIDER #2 (API 123-07689, Facility ID 239901; Loc ID 317743)	

County: WELD			
Township: 1N	Range: 67W	Section: 33	QQ: NWNW
Original Latitude/ Longitude: 40.012978 / -104.902532			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
<div style="border: 1px solid black; height: 100px; width: 100%;"></div>	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|-----------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 383024 | Date: 5/31/1973 |
| <input type="checkbox"/> | Field Inspection(s) – Doc #: | Date: |
| | Doc #: | Date: |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2542826 | Date: 5/18/1998 |
| <input checked="" type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: 118546, 118540, 118541 | |
| <input type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input checked="" type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

No evidence of a pit on location.

Pit Status Review Summary:

Based on records review and aerial imagery there is no evidence that there was a pit on location. 1979 letter (included in pit permit file) and 1998 pit inventory document that produced water goes to a tank at this location (shared battery). Pit Status has been changed to closed.

