

Pit Status Evaluation Form

Pit Overview:

Pit Name: MARIE A. FINDLAY	Facility ID: 118544
Current Status: Unknown	Status Date: 9/23/1999
Current Operator: AMOCO PRODUCTION COMPANY / 2500	
Updated Operator:	
Form 15 Pit Permit Doc #: 383034	Permit Date: 12/12/1974
Related Facilities: MARIE A. FINDLAY #1 (API 123-08147; Facility ID 240359; Loc ID 406275)	

County: WELD			
Township: 1N	Range: 67W	Section: 31	QQ: SWNE
Original Latitude/ Longitude: 40.009398 / -104.930833			
Updated Latitude/ Longitude: /			
Basis for Location Change:			

Pit Inspection/Information Request:

Field Inspection Date:	Document #:
Pit Still Present in Field: No	
Visible Surface Impacts: <input type="checkbox"/> Stressed Vegetation <input type="checkbox"/> Surface Depression <input type="checkbox"/> Stained Soil <input type="checkbox"/> Other (see below)	
Inspection Notes:	
Operator Required to Submit Form: NA	Due Date:
Form Request Sent To:	Sent Date:

Pit Status Evaluation:

Pit Status Review Documents:

- | | | |
|-------------------------------------|---|------------------|
| <input checked="" type="checkbox"/> | Form 15 Pit Permit – Doc #: 383034 | Date: 12/12/1974 |
| <input checked="" type="checkbox"/> | Field Inspection(s) – Doc #: 200050557 | Date: 3/1/2004 |
| | Doc #: | Date: |
| | Doc #: | Date: |
| <input type="checkbox"/> | Form 27 Remediation Workplan – Project #: | Date: |
| <input type="checkbox"/> | Form 4 Sundry Notice – Doc #: | Date: |
| <input type="checkbox"/> | COGIS Document – Doc #: | Date: |
| <input checked="" type="checkbox"/> | Pit Inventory – Doc #: 2142986 | Date: 8/25/1997 |
| <input type="checkbox"/> | Duplicate Record – Duplicate Pit(s) #: | |
| <input checked="" type="checkbox"/> | Aerial Photo Verification (photos attached) | |
| <input type="checkbox"/> | Other: | |

Pit Status Determination

Updated Pit Status: Closed

Pit Status Date: 9/23/1999

Timing of Pit Closure:

Closed prior to 1997 pit inventory.

Pit Status Review Summary:

Based on records review and aerial imagery, any pits on location were replaced by a fiberglass produced water tank prior to 1997 pit inventory report. Associate well PA 10/1/2002 and passed surface reclamation inspection 3/1/2004. Pit status has been changed to closed.

