

Inspection Photos

API: 071-07537

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/25/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07537 | Date: 11/25/2020

Inspection Photos



Photo 1. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07537 | Date: 11/25/2020

Inspection Photos



Photo 2. Well sign posted at meter shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07537 | Date: 11/25/2020

Inspection Photos



Photo 3. There are berms directed toward this rock rip/rap outlet along the fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07537 | Date: 11/25/2020