Inspection Photos

API: 071-06459

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 11/25/2020

COLORADO
Oil & Gas Conservation Commission
Department of Natural Resources

Photo 1. Facing west toward the location which has been reclaimed.

Photo 2. Facing southwest at the location. The vegetation is establishing and appears to reflect native vegetation.

Photo 3. Facing north at the location. The vegetation is progressing but has not reached 80% cover.