

Inspection Photos
Location Name: Rose 23-18
API: 05-125-08919



1. Location photo



2. Erosion on access