

Inspection Photos

Location Name: WELD COUNTY USX AB-67N64W /19SENE

Location #: 410070



Photo #1

Weld County USX AB 19-07PD (05-123-30265)
Wellsite

Temporarily Abandoned | TA



Photo #2

Weld County USX AB 19-08P (05-123-30107)
Wellsite

Temporarily Abandoned | TA

Inspection Photos

Location Name: WELD COUNTY USX AB-67N64W /19SENE

Location #: 410070



Photo #3

Weld County USX AB 19-07PD, 19-08P Battery site

Abandoned: ALL Equipment Removed