

# Interim Reclamation Inspection

November 25, 2020

Operator: K P KAUFFMAN COMPANY INC - 46290

API: 05-123-08219

Inspection Document #: 697502211

Weld County, CO

NENE Section 27 T2N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: VONASEK #3  
API: 05-123-08219



**Photo 1.** Photo taken illustrates the Operator well sign.



Inspection Photos  
Location Name: VONASEK #3  
API: 05-123-08219



**Photo 2.** Photo taken from the southern location, facing East. Photo illustrates the Operator has failed to comply with the previous corrective action to remove an unused pumping unit.