

Coral Production Corp, Miller 1-A
121-09221
Inspection #688309040
11/23/2020
Routine Inspection



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Colorado Oil and Gas Conservation Commission
39.76279, -102.97459, 4491.5ft, 158°
11/23/2020 01:14:16 PM




Colorado Oil and Gas Conservation Commission
39.76276, -102.97461, 4468.5ft, 159°
11/23/2020 01:14:23 PM




Colorado Oil and Gas Conservation Commission
39.76287, -102.97453, 4465.2ft, 202°
11/23/2020 01:14:36 PM



Colorado Oil and Gas Conservation Commission
39.763, -102.97465, 4455.4ft, 224°
11/23/2020 01:15:34 PM



Colorado Oil and Gas Conservation Commission
39.764, -102.97255, 4468.5ft, 228°
11/23/2020 01:18:21 PM



Colorado Oil and Gas Conservation Commission
39.76389, -102.97282, 4478.3ft, 97°
11/23/2020 01:18:04 PM



Colorado Oil and Gas Conservation Commission
39.76428, -102.97291, 4442.3ft, 132°
11/23/2020 01:16:39 PM



Colorado Oil and Gas Conservation Commission
39.76427, -102.97292, 4461.9ft, 273°
11/23/2020 01:17:01 PM



Colorado Oil and Gas Conservation Commission

39.76425, -102.97304, 4468.5ft, 251°

11/23/2020 01:17:24 PM